



TEST CERTIFICATE

FOR REPORT MT-09/040

CLIENT: ATF HIRE GROUP PTY LTD
LEVEL 2, QUAD 3, 102 BENNELONG ROAD
HOMEBUSH BAY NSW 2127

EQUIPMENT DESIGNATION: *Void Protection Platform*

MANUFACTURER: *ATF HIRE GROUP Pty Ltd*

APPLICABLE STANDARD: *AS/NZS 1576.1-1995
Scaffolding
Part 1 General Requirements*

APPLICABLE CLAUSE: *Clause 2.4.3.2 (a)*

COMMENTS:

The ATF "Void Protection Platform" as described in test report MT-09/040 has been load tested to 2 times the WLL (2.2kN) as required by AS/NZS 1576.1-1995 Clause 2.4.3.2 (a).

CONDITIONS:

- 1) Melbourne Testing Services Pty Ltd shall not be liable for loss, cost, damages or expenses incurred by the client or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Melbourne Testing Services Pty Ltd be liable for consequential damages including, but not limited to, lost profit, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested.
- 2) This report only indicates compliance of the void protection platform in its state at the time of testing. It should not be taken as a statement that all similar void protection platforms or components of void protection platforms in all states of repair, would also be found to comply.
- 3) It remains the responsibility of the client to ensure that the void protection platform is representative of production batches.
- 4) This report only covers the structural integrity of the void protection platform in accordance with the specific requirements of AS 1576.1-1995 Clause 2.4.3.2 (a).
- 5) This report is specific to the performance of the void protection platform as described herein for a light duty working platform.
- 6) MTS shall take no responsibility for the onsite installation and usage of the void protection platform as reported herein.
- 7) MTS shall take no responsibility for the interpretation or misinterpretation of the procedures outlined in AS 1576.1-1995 Clause 2.4.3.2 (a).
- 8) MTS shall take no responsibility for the compliance of the void protection platform or the overall performance of the void protection platform as required by AS 1576.1-1995 or any other standards that may apply.

RODNEY WILKIE
TEST ENGINEER
LABORATORY MANAGER

DATE: 27/02/2009